

Sewage Sludge (Biosolids) Annual Report

EPA Regulations - 503.18, 503.28, 503.48

INSTRUCTIONS

EPA's sewage sludge regulations (40 CFR part 503) require certain POTWs and Class I sewage sludge management facilities to submit to an annual biosolids report. POTWs that must submit an annual report include POTWs with a design flow rate equal to or greater than one million gallons per day, and POTWs that serve 10,000 people or more. This is the biosolids annual report form for POTWs and Class I sewage sludge management facilities in the 42 states and all tribes and territories where EPA administers the Federal biosolids program.

For the purposes of this form, the term 'sewage sludge' also refers to the material that is commonly referred to as 'biosolids.' EPA does not have a regulatory definition for biosolids but this material is commonly referred to as sewage sludge that is placed on, or applied to the land to use the beneficial properties of the material as a soil amendment, conditioner, or fertilizer. EPA's use of the term 'biosolids' in this form is to confirm that information about beneficially used sewage sludge (a.k.a. biosolids) should be reported on this form.

Please note that questions with a (*) are required. Please also note that EPA may contact you after you submit this report for more information regarding your sewage sludge program.

Questions regarding this form should be directed to the NPDES Electronic Reporting Helpdesk at:

• NPDESeReporting@epa.gov OR	
1-877-227-8965	

What action would you like to take? *

	New Biosolias Program Report
1. P	rogram Information
	Please select the NPDES ID number below for this Sewage Sludge (Biosolids) Annual Report. *
	WAL023744: BELLINGHAM STP
	IMPORTANT - If you do not see the NPDES ID associated with your facility (i.e., you only see a blue bar in the above drop down list), you MUST follow the instructions in the "Biosolids User's Guide." A shorter set of instructions to fix this issue are in the "Important Instructions on Accessing Your NPDES ID" document. Both documents are located at: https://epanet.zendesk.com/hc/en-us/sections/207108787-General-Biosolids .
	Facility Name: BELLINGHAM STP
	Street: 2221 Pacific St
	City: Bellingham
	State: WA
	Zip Code : 98229-5823
	1.1 Please select at least one of the following options pertaining to your obligation to submit a Sewage Sludge (Biosolids) Annual Report in compliance with 40 CFR 503. The facility is: *
	a POTW with a design flow rate equal to or greater than one million gallons per day a POTW that serves 10,000 people or more a Class I Sludge Management Facility as defined in 40 CFR 503.9
	otherwise required to report (e.g., permit condition, enforcement action)

1.2 Reporting Perio	od Start and End Dates	
Start Date of Repo	rting Period * End Date of Reporting Period *	
01-01-2017	12-31-2017	
2. Facility Information		
-	wage Sludge Treatment Processes	
more that apply). *		ocesses that you used on the sewage sludge or biosolids generated or produced at your facility during the reporting period (check one o
Pathogen Reduct	ion Operations (see Appendix B to Part 503)	Physical Treatment Operations
Processes to Signif	ficantly Reduce Pathogens (PSRP)	Preliminary Operations (e.g., sludge grinding, degritting, blending)
Aerobic Diges	tion	Thickening (e.g., gravity and/or flotation thickening, centrifugation, belt filter press, vacuum filter)
Air Drying (or	"sludge drying beds")	Sludge Lagoon
Anaerobic Dig	estion	Other Processes to Manage Sewage Sludge
Lower Temper	rature Composting	Temporary Sludge Storage (sewage sludge stored on land 2 years or less, not in sewage sludge unit)
Lime Stabilizat	tion	Long-term Sludge Storage (sewage sludge stored on land 2 years or more, not in sewage sludge unit)
Processes to Furth	er Reduce Pathogens (PFRP)	Methane or Biogas Capture and Recovery
Higher Tempe	erature Composting	Other Treatment Process: Incineration - multiple hearth sewage sludge incineration.
Heat Drying (e	e.g., flash dryer, spray dryer, rotary dryer)	
Heat Treatmer	nt (Liquid sewage sludge is heated to temp. of 356°F (or 180°C) o	higher for 30 min.)
Thermophilic A	Aerobic Digestion	
Beta Ray Irradi	iation	
Gamma Ray Iri	radiation	
Pasteurization	r	
2.2 Biosolids or Sev	wage Sludge Analytical Methods	
also specify the an	alytical methods that must be used to analyze samples of sewag	d to the land, placed on a surface disposal site, or fired in a sewage sludge incinerator must be collected and analyzed. These regulations sludge. For example, EPA requires facilities to monitor for the certain parameters, which are listed in Tables 1, 2, 3, and 4 at 40 CFR 503.1
and Tables 1 and 2	2 <u>40 CFR 503.23</u> . See also <u>40 CFR 503.8</u> .	
	ŭ ,	idge or biosolids generated or produced by you or your facility during the reporting period (check one or more that apply). *
Parameter	Method Number or Author	Description Text for Certification Section
Pathogens		
Ascaris ova.	Sludge Monitoring - Ascaris ova.	Sludge Monitoring - Ascaris ova., "Test Method for Detecting, Enumerating, and Determining the Viability Ascaris in Sludge (Appendix I)," Control of Pathogens and Vector Attraction in Sewage Sludge", EPA-625-R-92-013, July 2003

Other Ascaris ova. Analytical Method:

Parameter	Method Number or Author	Description Text for Certification Section							
Enteric viruses	ASTM Method D4994 - Enteric Viruses	ASTM Method D4994 - Enteric Viruses, "Standard Practice for Recovery of Viruses From Wastewater Sludges," ASTM International							
Effectic viruses	Other Enteric Viruses Analytical Method:								
	Standard Method 9222 - Fecal Coliform	Standard Method 9222 - Fecal Coliform, "Standard Methods for the Examination of Water and Wastewater," American Pub Health Association [Note: This method is only allowable for Class B sewage sludge]							
	Standard Method 9221 - Fecal Coliform	Standard Method 9221 - Fecal Coliform, "Standard Methods for the Examination of Water and Wastewater," American Public							
Fecal coliform	EPA Method 1680 - Fecal Coliform	Health Association EPA Method 1680 - Fecal Coliform, "Fecal Coliforms in Sewage Sludge by Multiple-Tube Fermentation using Lauryl Tryptose Broth							
	EPA Method 1681 - Fecal Coliform	and EC Medium," EPA-821-R-10-003, April 2010 EPA Method 1681 - Fecal Coliform, Fecal Coliforms in Sewage Sludge (Biosolids) by MultipleTube Fermentation using A-1							
	Other Fecal Coliform Analytical Method:	medium, EPA-821-R-04-027, June 2005							
Helminth ova.	W.A. Yanko Method - Helminth ova.	W.A. Yanko Method - Helminth Ova., "Occurrence of Pathogens in Distribution and Marketing Municipal Sludges," EPA-600-1-87-014, 1987							
Heilillitti Ova.	Other Helminth ova. Analytical Method:	2171300 107 011, 1707							
	Standard Method 9260 - Salmonella	Standard Method 9260 - Salmonella, "Standard Methods for the Examination of Water and Wastewater," American Public Health Association							
Salmonella sp. Bacteria	EPA Method 1682 - Salmonella	EPA Method 1682, "Salmonella in Sewage Sludge (Biosolids) by Modified Semisolid Rappaport-Vassiliadis (MSRV) Medium,"							
заппопена ѕр. вастена	Kenner and Clark Method - Salmonella	EPA-821-R-06-014, July 2006 Kenner and Clark Method - Salmonella, "Detection and Enumeration of Salmonella and Pseudomonas aeruginosa," J. Water							
	Other Salmonella sp. Bacteria Analytical Method:	Pollution Control Federation, 46(9):2163-2171, 1974							
Total Culturable Viruses	Class A Sludge Monitoring - Total Culturable Viruses	EPA Class A Sludge Monitoring - Total Culturable Viruses, "Method for the Recovery and Assay of Total Culturable Viruses fro Sludge (Appendix H)," Control of Pathogens and Vector Attraction in Sewage Sludge, EPA-625-R-92-013, July 2003							
Total Culturable viruses	Other Total Culturable Viruses Analytical Method:	classe v. ppss 19, solition of a division and vector madellion in servings strange, Er // ves it //2 010, addy 2000							
Metals									
	EPA Method 6010 - Arsenic (ICP-OES)	EPA Method 6010 - Arsenic (Inductively Coupled Plasma - Optical Emission Spectrometry), "Test Methods for Evaluating Solid Waste, Physical/Chemical Methods," EPA Pub. SW-846							
	EPA Method 6020 - Arsenic (ICP-MS)	EPA Method 6020 - Arsenic (Inductively Coupled Plasma - Mass Spectrometry), "Test Methods for Evaluating Solid Waste, Physical/Chemical Methods," EPA Pub. SW-846							
Arsenic	EPA Method 7010 - Arsenic (GF-AAS)	EPA Method 7010 - Arsenic (Graphite Furnace Atomic Absorption Spectrophotometry), "Test Methods for Evaluating Solid Waste,							
	EPA Method 7061 - Arsenic (AA-GH)	Physical/Chemical Methods," EPA Pub. SW-846 EPA Method 7061 - Arsenic (Atomic Absorption - Gaseous Hydride), "Test Methods for Evaluating Solid Waste, Physical/Chemical							
	Other Arsenic Analytical Method:	Methods," EPA Pub. SW-846							
	EPA Method 6010 - Beryllium (ICP-OES)	EPA Method 6010 - Beryllium (Inductively Coupled Plasma - Optical Emission Spectrometry), "Test Methods for Evaluating Solid Waste, Physical/Chemical Methods," EPA Pub. SW-846							
	EPA Method 6020 - Beryllium (ICP-MS)	EPA Method 6020 - Beryllium (Inductively Coupled Plasma - Mass Spectrometry), "Test Methods for Evaluating Solid Waste,							
Beryllium	EPA Method 7000 - Beryllium (FAAS)	Physical/Chemical Methods," EPA Pub. SW-846 EPA Method 7000 - Beryllium (Flame Atomic Absorption Spectrophotometry), "Test Methods for Evaluating Solid Waste, Physical/							
	EPA Method 7010 - Beryllium (GF-AAS)	Chemical Methods," EPA Pub. SW-846 EPA Method 7010 - Beryllium (Graphite Furnace Atomic Absorption Spectrophotometry), "Test Methods for Evaluating Solid							
	Other Beryllium Analytical Method	Waste, Physical/Chemical Methods," EPA Pub. SW-846							
	_								

Parameter	Method Number or Author	Description Text for Certification Section
	EPA Method 6010 - Cadmium (ICP-OES)	EPA Method 6010 - Cadmium (Inductively Coupled Plasma - Optical Emission Spectrometry), "Test Methods for Evaluating Solid Waste, Physical/Chemical Methods," EPA Pub. SW-846
	EPA Method 6020 - Cadmium (ICP-MS)	EPA Method 6020 - Cadmium (Inductively Coupled Plasma - Mass Spectrometry), "Test Methods for Evaluating Solid Waste,
	EPA Method 7000 - Cadmium (FAAS)	Physical/Chemical Methods," EPA Pub. SW-846 EPA Method 7000 - Cadmium (Flame Atomic Absorption Spectrophotometry), "Test Methods for Evaluating Solid Waste, Physical/
Cadmium	EPA Method 7010 - Cadmium (GF-AAS)	Chemical Methods," EPA Pub. SW-846
		EPA Method 7010 - Cadmium (Graphite Furnace Atomic Absorption Spectrophotometry), "Test Methods for Evaluating Solid
	EPA Method 7131 - Cadmium (GF-AAS)	Waste, Physical/Chemical Methods," EPA Pub. SW-846 EPA Method 7131 - Cadmium (Graphite Furnace Atomic Absorption Spectrophotometry), "Test Methods for Evaluating Solid
	Other Cadmium Analytical Method:	Waste, Physical/Chemical Methods," EPA Pub. SW-846
	EPA Method 6010 - Chromium (ICP-OES)	EPA Method 6010 - Chromium (Inductively Coupled Plasma - Optical Emission Spectrometry), "Test Methods for Evaluating Solid Waste, Physical/Chemical Methods," EPA Pub. SW-846
	EPA Method 6020 - Chromium (ICP-MS)	EPA Method 6020 - Chromium (Inductively Coupled Plasma - Mass Spectrometry), "Test Methods for Evaluating Solid Waste,
	EPA Method 7000 - Chromium (FAAS)	Physical/Chemical Methods," EPA Pub. SW-846 EPA Method 7000 - Chromium (Flame Atomic Absorption Spectrophotometry), "Test Methods for Evaluating Solid Waste,
Chromium	EPA Method 7010 - Chromium (GF-AAS)	Physical/Chemical Methods," EPA Pub. SW-846
	EPA Method 7191 - Chromium	EPA Method 7010 - Chromium (Graphite Furnace Atomic Absorption Spectrophotometry), "Test Methods for Evaluating Solid Waste, Physical/Chemical Methods," EPA Pub. SW-846
	(AA-FT)	EPA Method 7191 - Chromium (Atomic Absorption - Furnace Technique), "Test Methods for Evaluating Solid Waste, Physical/
	Other Chromium Analytical Method:	Chemical Methods," EPA Pub. SW-846
	EPA Method 6010 - Copper (ICP-OES)	EPA Method 6010 - Copper (Inductively Coupled Plasma - Optical Emission Spectrometry), "Test Methods for Evaluating Solid Waste, Physical/Chemical Methods," EPA Pub. SW-846
	EPA Method 6020 - Copper (ICP-MS)	EPA Method 6020 - Copper (Inductively Coupled Plasma - Mass Spectrometry), "Test Methods for Evaluating Solid Waste, Physical/Chemical Methods," EPA Pub. SW-846
Copper	EPA Method 7000 - Copper (FAAS)	EPA Method 7000 - Copper (Flame Atomic Absorption Spectrophotometry), "Test Methods for Evaluating Solid Waste, Physical/
	EPA Method 7010 - Copper (GF-	Chemical Methods," EPA Pub. SW-846 EPA Method 7010 - Copper (Graphite Furnace Atomic Absorption Spectrophotometry), "Test Methods for Evaluating Solid Waste,
	AAS) Other Copper Analytical Method:	Physical/Chemical Methods," EPA Pub. SW-846
	EPA Method 6010 - Lead (ICP-OES)	EPA Method 6010 - Lead (Inductively Coupled Plasma - Optical Emission Spectrometry), "Test Methods for Evaluating Solid Waste, Physical/Chemical Methods," EPA Pub. SW-846
	EPA Method 6020 - Lead (ICP-MS)	EPA Method 6020 - Lead (Inductively Coupled Plasma - Mass Spectrometry), "Test Methods for Evaluating Solid Waste, Physical/
	EPA Method 7000 - Lead (FAAS)	Chemical Methods," EPA Pub. SW-846 EPA Method 7000 - Lead (Flame Atomic Absorption Spectrophotometry), "Test Methods for Evaluating Solid Waste, Physical/
Lead	EPA Method 7010 - Lead (GF-AAS)	Chemical Methods," EPA Pub. SW-846
	EPA Method 7421 - Lead (AA-FT)	EPA Method 7010 - Lead (Graphite Furnace Atomic Absorption Spectrophotometry), "Test Methods for Evaluating Solid Waste, Physical/Chemical Methods," EPA Pub. SW-846
	Other Lead Analytical Method:	EPA Method 7421 - Lead (Atomic Absorption - Furnace Technique), "Test Methods for Evaluating Solid Waste, Physical/Chemical Methods," EPA Pub. SW-846
	EPA Method 7471 - Mercury (CVAA)	EPA Method 7471 - Mercury in Solid or Semi-Solid Waste (Cold Vapor Atomic Absoprtion), "Test Methods for Evaluating Solid
Mercury	Other Mercury Analytical Method:	Waste, Physical/Chemical Methods," EPA Pub. SW-846

Parameter	Method Number or Author	Description Text for Certification Section						
	EPA Method 6010 - Molybdenum (ICP-OES)	EPA Method 6010 - Molybdenum (Inductively Coupled Plasma - Optical Emission Spectrometry), "Test Methods for Evaluating Solid Waste, Physical/Chemical Methods," EPA Pub. SW-846						
	EPA Method 6020 - Molybdenum (ICP-MS)	EPA Method 6020 - Molybdenum (Inductively Coupled Plasma - Mass Spectrometry), "Test Methods for Evaluating Solid Waste, Physical/Chemical Methods," EPA Pub. SW-846						
Molybdenum	EPA Method 7000 - Molybdenum (FAAS)	EPA Method 7000 - Molybdenum (Flame Atomic Absorption Spectrophotometry), "Test Methods for Evaluating Solid Waste, Physical/Chemical Methods," EPA Pub. SW-846						
,	EPA Method 7010 - Molybdenum (GF-AAS)	EPA Method 7010 - Molybdenum (Graphite Furnace Atomic Absorption Spectrophotometry), "Test Methods for Evaluating Solid						
	EPA Method 7481 - Molybdenum	Waste, Physical/Chemical Methods," EPA Pub. SW-846						
	(AA-FT) Other Molybdenum Analytical Method:	EPA Method 7481 - Molybdenum (Atomic Absorption - Furnace Technique), "Test Methods for Evaluating Solid Waste, Physical/Chemical Methods," EPA Pub. SW-846						
	EPA Method 6010 - Nickel (ICP-OES)	EPA Method 6010 - Nickel (Inductively Coupled Plasma - Optical Emission Spectrometry), "Test Methods for Evaluating Solid Waste, Physical/Chemical Methods," EPA Pub. SW-846						
	EPA Method 6020 - Nickel (ICP-MS)	EPA Method 6020 - Nickel (Inductively Coupled Plasma - Mass Spectrometry), "Test Methods for Evaluating Solid Waste, Physical/						
Nickel	EPA Method 7000 - Nickel (FAAS)	Chemical Methods," EPA Pub. SW-846 EPA Method 7000 - Nickel (Flame Atomic Absorption Spectrophotometry), "Test Methods for Evaluating Solid Waste, Physical/						
	EPA Method 7010 - Nickel (GF-	Chemical Methods," EPA Pub. SW-846 EPA Method 7010 - Nickel (Graphite Furnace Atomic Absorption Spectrophotometry), "Test Methods for Evaluating Solid Waste,						
	AAS) Other Nickel Analytical Method:	Physical/Chemical Methods," EPA Pub. SW-846						
	EPA Method 6010 - Selenium (ICP-OES)	EPA Method 6010 - Selenium (Inductively Coupled Plasma - Optical Emission Spectrometry), "Test Methods for Evaluating Solid Waste, Physical/Chemical Methods," EPA Pub. SW-846						
	EPA Method 6020 - Selenium (ICP-MS)	EPA Method 6020 - Selenium (Inductively Coupled Plasma - Mass Spectrometry), "Test Methods for Evaluating Solid Waste, Physical/Chemical Methods," EPA Pub. SW-846						
	EPA Method 7010 - Selenium (GF-AAS)	EPA Method 7010 - Selenium (Graphite Furnace Atomic Absorption Spectrophotometry), "Test Methods for Evaluating Solid						
Selenium	EPA Method 7740 - Selenium (AA-FT)	Waste, Physical/Chemical Methods," EPA Pub. SW-846						
	EPA Method 7741 - Selenium	EPA Method 7741A - Selenium (Atomic Absorption - Furnace Technique), "Test Methods for Evaluating Solid Waste, Physical/Chemical Methods," EPA Pub. SW-846						
	(AA-GH)	EPA Method 7741 - Selenium (Atomic Absorption - Gaseous Hydride), "Test Methods for Evaluating Solid Waste, Physical/Chemical						
	Other Selenium Analytical Method:	Methods," EPA Pub. SW-846						
	EPA Method 6010 - Zinc (ICP-OES)	EPA Method 6010 - Zinc (Inductively Coupled Plasma - Optical Emission Spectrometry), "Test Methods for Evaluating Solid Waste, Physical/Chemical Methods," EPA Pub. SW-846						
	EPA Method 6020 - Zinc (ICP-MS)	EPA Method 6020 - Zinc (Inductively Coupled Plasma - Mass Spectrometry), "Test Methods for Evaluating Solid Waste, Physical/ Chemical Methods," EPA Pub. SW-846						
Zinc	EPA Method 7000 - Zinc (FAAS)	EPA Method 7000 - Zinc (Flame Atomic Absorption Spectrophotometry), "Test Methods for Evaluating Solid Waste, Physical/						
	EPA Method 7010 - Zinc (GF-AAS)	Chemical Methods," EPA Pub. SW-846 EPA Method 7010, 7 inc (Crapbite Europea Atomic Abcorption Spectrophotometry), "Test Methods for Evaluating Solid Waste						
	Other Zinc Analytical Method:	EPA Method 7010 - Zinc (Graphite Furnace Atomic Absorption Spectrophotometry), "Test Methods for Evaluating Solid Waste, Physical/Chemical Methods," EPA Pub. SW-846						
Nitrogen Compoun	ds							
	EPA Method 350.1 - Ammonia Nitrogen	EPA Method 350.1 - Ammonia Nitrogen, "Determination of Ammonia Nitrogen by Semi-Automated Colorimetry," August 1993						
Ammonia Nitrogen	Standard Method 4500-NH3 - Ammonia Nitrogen	Standard Method 4500-NH3 - Ammonia Nitrogen, "Standard Methods for the Examination of Water and Wastewater," American Public Health Association						
	Other Ammonia Nitrogen Analytical Method							
	EPA Method 9056 - Nitrate Nitrogen (IC)	EPA Method 9056 - Nitrate Nitrogen (Ion Chromatography), "Test Methods for Evaluating Solid Waste, Physical/Chemical Methods," EPA Pub. SW-846						
Nitrate Nitrogen	EPA Method 9210 - Nitrate Nitrogen (ISE)	EPA Method 9210 - Nitrate Nitrogen (Ion-Selective Electrode), "Test Methods for Evaluating Solid Waste, Physical/Chemical						
	Other Nitrate Nitrogen Analytical Method:	Methods," EPA Pub. SW-846						

Parameter	Method Number or Author	Description Text for Certification Section						
	Standard Method 4500-N - Nitrogen	Standard Method 4500-N - Nitrogen, "Standard Methods for the Examination of Water and Wastewater," American Public Health Association						
Nitrogen	Other Nitrogen Analytical Method:	Association						
	Standard Method 4500-Norg - Organic Nitrogen	Standard Method 4500-Norg - Organic Nitrogen, "Standard Methods for the Examination of Water and Wastewater," American						
Organic Nitrogen	Other Organic Nitrogen Analytical Method:	Public Health Association						
	EPA Method 351.2 - Total Kjeldahl Nitrogen	EPA Method 351.2 - Total Kjeldahl Nitrogen, "Determination of Total Kjeldahl Nitrogen by Semi-Automated Colorimetry," August 1993						
Total Kjeldahl Nitrogen	Other Total Kjeldahl Nitrogen Analytical Method:							
Other Analytes								
• • • • • • • • • • • • • • • • • • •		Standard Method 2540 - Total, fixed, and volatile solids, "Standard Methods for the Examination of Water and Wastewater,"						
Fixed Solids	Standard Method 2540 - Fixed Solids	American Public Health Association						
	Other Fixed Solids Analytical Method:	FDA Makkad 2005 Deint Filter Liewide Teet "Teet Mathade for Fuelvation Calid Weets Dhyrical Charries Mathade" FDA Dub						
Paint Filter Test	EPA Method 9095 - Paint Filter Liquids Test	EPA Method 9095 - Paint Filter Liquids Test, "Test Methods for Evaluating Solid Waste, Physical/Chemical Methods," EPA Pub. SW-846						
	Other Paint Filter Test Analytical Method:							
	EPA Method 9040 - pH (≤ 7% solids)	EPA Method 9040 - pH (≤ 7% solids), "Test Methods for Evaluating Solid Waste, Physical/Chemical Methods," EPA Pub. SW-846						
рН	EPA Method 9045 - pH (> 7% solids)	EPA Method 9045 - pH (> 7% solids), "Test Methods for Evaluating Solid Waste, Physical/Chemical Methods," EPA Pub. SW-846						
	Other pH Analytical Method:							
Specific Oxygen Uptake	Standard Method 2710 - SOUR	Standard Method 2710 - Specific Oxygen Uptake Rate, "Standard Methods for the Examination of Water and Wastewater," American Public Health Association						
Rate	Other Specific Oxygen Uptake Rate Analytical Method:							
70.5	EPA Method 1311 - Toxicity Characteristic Leaching EPA Method 1311 - Toxicity Characteristic Leaching Procedure, "Test Methods for Evaluating Solid Waste, Physics of the Company of the							
TCLP	Procedure Other TCLP Analytical Method:	Methods," EPA Pub. SW-846						
- ·	Standard Method 2550 - Temperature	Standard Method 2550 - Temperature, "Standard Methods for the Examination of Water and Wastewater," American Public Health Association						
Temperature	Other Temperature Analytical Method:	A BOODING TO						
Takal Callala	Standard Method 2540 - Total Solids	Standard Method 2540 - Total, fixed, and volatile solids, "Standard Methods for the Examination of Water and Wastewater," American Public Health Association						
Total Solids	Other Total Solids Analytical Method:	Affercant ubic fleatif Association						
	Standard Method 2540 - Volatile Solids	Standard Method 2540 - Total, fixed, and volatile solids, "Standard Methods for the Examination of Water and Wastewater," American Public Health Association						
Volatile Solids	Other Volatile Solids Analytical Method:	Afficiant ubic ficaliti Association						
No Analytical Methods	No Analytical Methods Used							
2.2 What is the patients	A total values of biocalide or covers sludge produced at visus for	illity for the reporting period (in dry metric tens)?						
3703.5	d total volume of biosolids or sewage sludge produced at your fac	inity for the reporting period (in dry metric toris)?						
1								

3. Biosolids or Sewage Sludge Management

EPA NPDES regulations at 40 CFR 503 only require reporting for land application, surface disposal, or incineration. You have the option to select "Other Management Practice" if you wish to provide more information on how you manage your sewage sludge or biosolids.

Please use the selections below to identify how sewage sludge or biosolids generated or produced at your facility was managed, used, or disposed by you or your facility for the reporting period. You can use the button below to add as many Sewage Sludge Unique Identifier (SSUID) sections as needed to describe how you manage your sewage sludge.

SSUID Section

Sewage Sludge Unique Identifier (SSU	JID): 001						
Management Practice Type *	Handler, Preparer, or Applier Type *						
Incineration	On-Site Owner or Operator						
• •	the distribution and marketing (sale or give away) of Class A EQ. "Off-Site Third-Party Handler or Applier" refers to third parties which do not change the quality of the Biosolids. "Off-d party which changes the quality of the Biosolids.						
Bulk or Bag/Container *	Volume Amount (dry metric tons) *						
Not Applicable	3703.5						
Noncompliance Reporting							
prepares sewage sludge (i.e., person who	dicate any noncompliance with EPA's Federal sewage sludge program requirements (see 40 CFR 503) for this facility during the reporting period. EPA notes that any person who io generates sewage sludge or a person who derives a material from sewage sludge) shall ensure that the applicable requirements in EPA's biosolids regulations (40 CFR 503) are met ne land, placed on a surface disposal site, or fired in a sewage sludge incinerator (see 40 CFR 503.7).						
Incineration							
Facility failed to comply with emission	ons limits as specified in the NPDES permit or 40 CFR 503.43.						
Facility failed to properly collect and analyze its sewage sludge in accordance with the required monitoring frequency and approved analytical methods in order to obtain an accurate and representative sample (including appropriate method holding times) (see permit requirements and 40 CFR 503.8).							
Facility failed to comply with the National Emission Standards for Beryllium in Subpart C of 40 CFR Part 61.							
Facility failed to comply with the Na	ational Emission Standards for Mercury in Subpart E of <u>40 CFR Part 61</u> .						
Facility failed to operate, maintain, 503.45).	and calibrate the instruments that continuously measure and record THC (or alternatively CO), oxygen concentration, moisture content, and combustion temperatures (see 40 CFR						
Facility incinerator failed to operate	within the required range of the air pollution control devices operating parameters as specified in the permit.						
Incineration of sewage sludge likely adversely affected a threatened or endangered species listed under section 4 of the Endangered Species Act or its designated critical habitat (see 40 CFR 503.45(g)).							
Facility did not comply with one or r	more of the applicable incineration requirements (see 40 CFR 503.45(a) through (f) and (h)).						
Please select this chec	kbox to continue completing the form. the SSUID section(s) above, uncheck this box.*						

4. Incineration

Please complete the following tables for the on-site sewage sludge incineration conducted by you or your facility. Please use the instructions in the "Biosolids User's Guide" to complete this section. See: https://epanet.zendesk.com/hc/en-us/sections/207108787-General-Biosolids.

Pollutant				ration ncentration in Stad on in Sewage Sludç			Calcula	ted Limit		Pai	rameter Units		
Arsenic	3.0				14	125		mg/kg db					
Beryllium			0				Ę	58		ug/m3			
Cadmium			1.3	3			4439			mg/kg db			
Chromium			20)			4552				mg/kg db		
Lead			18	}			45	461		mg/kg db			
Mercury			31				18	521		ug/dscm @ 7%			
Nickel	14.3				144470			mg/kg db					
Please Report One Parameter	Monthly Average Concentration (Parts Per Million on Volumetric Pacis)												
	Jan	Feb	Mar	April	May	Jun	Jul	Aug	Sep	Oct	Nov	Dec	
Total Hydrocarbon Concentration in Exit Gas	3.5	3.6	4.8	5.1	11.4	16.6	11.7	7.6	9.4	8.7	12.8	17.7	
Carbon Monoxide Concentration in Exit Gas (per <u>40</u> <u>CFR 503.40(c)(1)</u>)													
Miminic			Miminiun	um Maximum				Parameter Units					
Operating Combustion Temperature		1501			1733			F					
Moisture Content in Exit Gas			1.4				2.4			%			
Oxygen Concentration			11.0				14.7			%			

Additional Information

Please enter any additional information in the comment box below (limit to 3,900 characters) that you would like to provide.

Hg measured in stack #1 gas at 0.031 mg/dscm @ 7% O2 (and at 0.022 mg/dscm @ 7% O2 in stack #2) during 2017 40 CFR 62 LLL testing. Beryllium < DL (<0.053 ug/m3) in New Source Performance Testing. Note: No guidance found for the specific reporting parameters: Moisture or O2. Used 40 CFR 62 LLL data for moisture and O2, Bellingham also provided 2017 incinerator daily averages to USEPA's Region 7 Biosolids Center in report mailed 1/15/18.

Additional Attachments (maximum size 25 MB)

File: BellinghamIncinAves2017.zip

Certification Information

certify, under penalty of law, that the information in this report was prepared under my direction and supervision in accordance with the system designed to ensure that qualified personnel properly gather and evaluate
this information. Lam aware that there are significant penalties for false certification including the possibility of fine and imprisonment

Certifier E-Mail *	Form Action *
klowry@cob.org	Approve